

## INSTRUCTIONS FOR UPDATING SW VERSION 5.5 BLUE&ME

**WARNING** If Blue&Me™ works properly with phones connected and there is no need to listen to music files from new Apple™ products such as iTouch or iPhone, proceeding with the new software update is not recommended.

If your car is recently produced it may already be up-to-date, if in doubt install the update of version 5.5, in this case the procedure will last for a few seconds

This update it's NOT available for the Blue&Me NAV version

The update process is an operation to be performed with maximum attention to the instructions. In the event of errors the system may not work.

Remember that once this procedure has been performed it will not be possible to return to the previous software version.

1. From the official FGA website [www.fiat.com](http://www.fiat.com) access the **Blue&Me™** section and download the .zip file containing the update application. [The total size of the files to be downloaded is 50 Mb]
2. Unzip the .zip file downloaded into a suitable dedicated directory (e.g. c:\Blue&Me). At the end check that the following files are present:
  - **install.inf**
  - **82UP**
  - **C82E.cab**
  - **C82S\_v11.cab**
  - **COU.pku**
  - **DEU.pku**
3. Prepare a USB memory stick, with a capacity of at least 128 Mb, **formatting the memory in FAT32** mode to delete all the data previously contained.

**NOTE** It is advisable to use a USB storage device with a capacity of less than 8 Gb.

4. Store the files previously downloaded in the USB stick main directory (folder), checking that they have all been copied correctly, the update process fails if the file are stored on a USB key folder.

**WARNING** Before starting the update the mobile phone needs to be turned off

**During the software update phase the steering wheel buttons shouldn't be pressed!**

The update time depends on the car and the USB memory model, on average, it can vary from 5 to 15 minutes.

5. With the car stationary and the ignition key in the **STOP** position, insert the memory stick in the **Blue&Me™** USB port situated on the centre console or in the glove compartment box.  
(The update is not available for cars NOT fitted with a USB media player port, do not use the USB diagnosis port present on the control unit)
6. Turn the ignition key to the **MAR** position, WITHOUT STARTING THE CAR, turn the radio on taking care to remove any warning messages (e.g. door open...) on the display by pressing the "Mode" or "Menu" button (depending on the car to be updated).

**WARNING** *Never extract the memory stick from the USB port for any reason before the software update procedure has finished properly!*

**The stick should remain inserted even if the information "RE-START..." appears on the panel then followed by the date and time and the radio starts to play again even for a few minutes.**

7. On the display of the control panel the message: "**UPDATE IN PROGRESS**" will be displayed and the voice message "**update started**" will be played . If this does not happen turn the key to the **STOP** position and then **MAR** again. During the update some messages on the progression of the process will be displayed.
8. When the update is over the message "**COMPLETE**" will be displayed on the control panel and the voice message "**update complete, remove the USB stick**" will be played.
9. The **Blue&Me™** update process is complete, turn the ignition key to the **STOP** position and extract the USB stick.

If the update is not complete the message "USB xx error" will appear on the display and the following voice message will be played: "There was an error during the update". In this case repeat the procedure starting again from point 1.

**NOTE** *Some menu item have been changed compared to the previous version. The changes are shown below:*

**Before:** M.M. PLAYER

**Before:** CONTINUOUS PLAY

**Before:** DEVICE UPDATE

**Now:** MEDIA PLAYER

**Now:** REPEAT TRACK

**Now:** (item removed)

**WARNING** Once the update has finished, connection with phones already previously connected will automatically happen without intervention, for the first few connections immediately after the update some disconnections from the Bluetooth connection may occur, as **Blue&Me™** will test various connection protocols to find the best one for the type of phone.

On some phones that support a particular protocol (PBAP) the contact list will be displayed as Name and Surname regardless of how it is displayed on your phone.

The update does not improve compatibility with AAC and MP4 where not already present on the car when delivered.

For the correct action of the music files reproduction we suggest to use USB keys that contain only audio files; the presence of executable files or other programs installation could delays or blocks the reproduction